




4510 WIRING DIAGRAM




4510 WIRING DIAGRAM




CABIN WIRING DIAGRAM 1.



CABIN WIRING DIAGRAM 2.



- Drawing for fixing position of the fuse
- Wiring diagram of the electric instrument



1	Fuse box
2	3 pieces of fuse blinks
3	Power for the working
5	Units for direction Signal relay for the power
6	PTO monitor PTO safety relay
7	Coupler for the power Max rated ampere
8	Coupler for the trailer

A	Head lamp	12V45/45W
B	Direction signal lamp	12V21W
	Stop lamp back light	21/5W
C	Meta panel light	12V3.4W
D	Working lamp	12V35W
E	Direction signal lamp	12V21W
	Side lamp	21V5W
F	Back lamp	12V20W
G	Number lamp	12V10W

Wiring diagram of Independent PTO

